TEXAS COMMISSION ON JAIL STANDARDS JAIL INSPECTION REPORT

			JAIL INSP	ECTION REPORT				
Facility Name:		Midland County Jail		I	Date:		July 21, 2020	
Item	Section	Paragraph	Comments					
·			Facility Maintenance. conducted to ensure a semantic conducted to ensure a semantic conducting the variety were identified: Tent No water pressure from Toilet/Sink Combo #3 Toilet #4 not flushing. Shower #1 not working. Shower #3 no hot wate. Shower #4 no hot wate. Shower #6 not working. J-Block Toilet/Sink Combo #1 Toilet/Sink Combo #7 H-Block	Preventive maintenance afe, secure, and sanitary walk-through of the faciont 3 sinks. In no cold water. Ing. Iter.	e, to include / facility. i lity, the follov	necessary repairs		
			• First 5 showers clogg	ged.				
			• Toilet #3 Clogged.	ido)				
			 Drain clogged (east s G-Block 	ide).				
			• Shower #6 no hot wat	ter.				
			• Shower #5 clogged.					
			• Toilet/Sink Combo #1	-3, 6 no pressure H/C.				
			T - ! - 4/0! - - 0 1 #0					

• Toilet/Sink Combo #6 low pressure H/C.

• Mop sink clogged.

TEXAS COMMISSION ON JAIL STANDARDS JAIL INSPECTION REPORT

Kitchen

- · Leak on a sink.
- · Leak on hand washing station.
- Eye Wash Station low water pressure.

B-Block

- Toilet #9 clogged.
- Toilet #3-4 do not work.
- Toilet/Sink Combo #2 no cold water.
- Toilet/Sink #15 low pressure H/C.
- Toilet #19 off.
- Toilet/Sink Combo #20 no hot water.
- Toilet/Sink Combo #23 low pressure HOT water.
- Multi-Purpose Room Toilet clogged with shredded book.

A-Block

- Day room middle toilet does not flush.
- Toilet #1 & 2 flushes comes up in opposite cell.
- Toilet #4 OFF.
- Toilet #7 low pressure H/C.
- Toilet #10 continuous water running.

C1-Block

- Day room toilet #1 no cold.
- #2 does not flush.
- #3 Low pressure H/C.
- Hole in corner.

C2-Block

• Shower turned off by staff because of leak.

D1-Block

- Middle toilet does not flush.
- Shower #2 does not turn on.
- Toilet/Sink Combo #1 no hot water.
- Cell #8 cold water.

Jason Jouett, TCJS Inspector